


# DEGRADATION STUDY OF FIELDDED PV MODULES FROM DIFFERENT CLIMATES IN CHINA



Dec 8<sup>th</sup>, 2015

Xian Dong


Shunde SYSU Institute for Solar Energy

# Outlin

---

- 1. Introduction**
- 2. Work about reliability of PV modules**
- 3. Degradation mechanism**
- 4. Summary & Outlook**

# 1. Introduction



# Collaboration platforms

---


- **State Key Laboratory of Optoelectronic Materials and Technologies**
- **South China Branch of NERCCE (National Engineering Research Center of Renewable Energy)**
- **Guangdong Provincial Key Laboratory of Photovoltaic Technologies**
- **Cooperation Base of CPVT (National Center of Supervision and Inspection on Solar Photovoltaic Products Quality) and Sun Yat-Sen University**
- **Key Laboratory of Solar Energy of Education Department, Guangdong Province**
- **Cooperating with multiple enterprises**

## 2. Work about reliability of PV modules

- Why and how we do these work
- Distribution of experimental systems
- Collections of fielded PV modules
- Re-installation of fielded modules

## 2. Work about reliability of PV modules

The Global PV market progressed in 2014: after three years of 30's GW of installation annually, reached 40 GW in 2014.  
(EPIA)




China is the world's biggest PV market now!



# Why and how we do these work

- **Reliability** and **Life-cycle** of modules are key points for PV systems
- **Scheme of quality assessment for PV modules**
- **Set up a performance appraisal system for PV products**



# Distribution of experimental PV modules



No.	Module	Location
1	Poly-Si	Guangzhou
2	Amorphous	Guangzhou
3	Mono-Si	Guangzhou
4	CIGS	Guangzhou
5	CdTe	Guangzhou
6	HIT	Guangzhou
7	Poly-Si	Guangzhou
8	mono,double glass	Guangzhou
9	a-Si (5%)	Guangzhou
10	a-Si (25%)	Guangzhou
11	a-Si (25%)	Guangzhou
12	Poly-Si	Qiqihaer
13	Mono/Poly	Xining
14	Mono-Si	Guilin
15	Poly-Si	Xichang
16	Poly-Si	Shunde
17	Poly-Si	Shunde
18	Poly-Si	Shunde





Comparison of different technologies



Appearance of Kyocera module systems



BIPV installation at SYSU (east campus)



Re-installation of fielded Solarex modules



Xining, Qinghai (2011-)



Qiqihaer, Heilongjiang (2011- )




Xichang, Sichuan (2013 - )



Guilin, Guangxi (2012- )

# Distribution of 6 climates types in China

(cold- xerothermic - cold-warm - warm- sub-humid heat - hygrothermal)



本图上中国国界线系按照地图出版社1980年出版的《中华人民共和国地图》绘制。


(From: GB/T 4797.1-2005 Environmental conditions appearing in nature of electric and electronic products- Temperature and humidity)

# Collection of fielded PV modules

Module information					testing method					
Type	Model	Location	Qty	Age	IV <sup>1*</sup>	IV <sup>2*</sup>	EL	IR	Material test	Notes
Poly	Solarex	Haikou	177	30	√		√	√	√	re-used
Mono	BP270	Shenzhen	50	28	√		√	√	√	re-used
	SM55	Shenzhen	2051	20	√		√	√	√	re-used
	M75	Dunhuang	100+	23	√	√	√	√		
	SP75	Dunhuang	10	15		√	√			
	M75	Haixi	112	23	√	√	√			
	SP75	Zhangye	96	15		√		√		
	S(M)55	Baiyin	80	18		√		√		
	SM55	Longnan <sup>1</sup>	64	17		√		√		
	SM55	Longnan <sup>2</sup>	60	17		√		√		
	Shell 85-P	Longnan <sup>2</sup>	20	15		√		√		

(IV<sup>1\*</sup>:STC test; IV<sup>2\*</sup>:outdoor test)












## Re-installation of Siemens modules

- ❑ Modules of the same batch worked in different climates were studied.
- ❑ 13 PV systems would be re-installed with these 17-year-old modules in typical climate locations.



# 3. Degradation mechanism

---

- Failure from terminal connection
- Failure from Al-frame, silicone sealant
- Degradation from pollutant
- Degradation from encapsulant material-2 cases
  - case 1: Tracking degradation of Solarex modules
  - case 2: Compare of Siemens modules from different climates

## Failure from terminal connection

### Statistical analysis of appearance defects for 177 Solarex modules in 2009

Appearance defects	Ratio (%)	Remarks
Appearance crack, bending or broken	79.7	including backsheet crack
Broken cells	1.7	-
Cell cracks	63.3	possible crack or snail trails
Junction box rusty	12.4	3.4% without output
Delaminated of EVA	57.6	bubbles inside EVA
Cable failures	2.8	no cable or without outer plastic protect
Diode failures	2.8	
Yellow/brown appearance	100	encapsulation material aging
Dirt or dust on the surface glass	100	part of them could be cleaned

**Degradation of encapsulant material**  
**Sealability of J-box**



6/177 modules failed for bad terminal connection-Solarex module produced in 1982

Improvement of quality and process for J-box after 1990s.

Diodes and J-box failure-PVQAT

DC1500V module

# Failure from Al-frame and silicone sealant



**GLASS BREAKAGE**





# Degradation from pollutant




**DUST OR BIRDS DROPPING**





# Case1: Tracking degradation of Solarex modules



## Poly module

- Glass: 3.2mm
- EVA
- laminated
- Backsheet: Tedlar only
- Solar cell: thickness  $425\mu\text{m}$ , size  $101 \times 101\text{mm}$
- Rated value:



$P=42.6\text{Wp}$

$V_{oc}=20.8\text{V}$

$I_{sc}=3.04\text{A}$

$V_m=15.1\text{V}$

$I_m=2.82\text{A}$



## HISTORY

Procuce: 1982

Installation: 1985

Location: Hainan (1985-2008)

$18^{\circ} 23' \sim 18^{\circ} 50' \text{N}$ ,

$108^{\circ} 36' \sim 109^{\circ} 05' \text{E}$

➤ Sub-tropic climate

➤ sub-humid heat climate

Location: Guangzhou (2010-)

$23^{\circ} 3' \text{N}$ ,

$113^{\circ} 22' \text{E}$

➤ Sub-tropic climate


➤ Sub-humid heat climate



Hainan (1985-2008, off-grid)



144 modules  
re-installed in Guangzhou



Guangzhou (2010-, on-grid)

### Historical meteorological data of the two places

Place	$\bar{T}$ (°C)	$\bar{T}_d$ (°C)	$\bar{T}_n$ (°C)	$\bar{R}$ (%)	$\bar{\xi}$ (hour)	year
HK	24.2	28.0	21.3	84	2070	1971-2000
GZ	22.1	26.7	19.3	78	1617	2001-2010




Degradation of 22-year-old multi-crystalline Si modules(1986-2008)

	Pm/W	Im/A	Vm/V	Isc/A	Voc/V	FF
Rated values	42.6	2.82	15.1	3.02	20.8	0.68
Actual values	39.7	2.50	15.9	2.8	20.3	0.7
Relative ratio	93.9	88.7	105.2	92.1	97.5	103.9

(171 modules, for 6 modules with rusty-broken junction-box leading to no electrical output)

**Decrease by current**



**144 selected modules were tested in 2009, 2014, 2015 at standard test condition**

Degradation Ratio to the rated value


Test time	Pm	Im	Vm	Isc	Voc
2009	0.96	0.88	1.1	0.91	0.98
2014	0.95	0.86	1.1	0.89	0.99
2015	0.94	0.86	1.1	0.89	0.99

## EVA Analysis


	method	reference	aged module
crosslinking-degree	exylene extraction	80-90	73 (marginal part)
light transmittance	ultraviolet spectrophotometer	91-93	<80
melting point	DSC	62-72	71
heat of solidification	DSC	5	0.54
VA content	TGA	28-33	33
PH	PH meter	5.69	5.09
yellowness index	colorimeter	0.9	11.5
tensile strength	Electronic Pull and Push Strength Caculator	18	3
breakage elongation		800	697
IR	IR spectrophotometer	-	acetic acid



Light transmittance comparison of surface encapsulant



Crosslink degree of EVA from different parts in the module



73.43%

94.86%




**THEORY**

**≠**

**REALITY**





## Back-sheet analysis Solarex/BP270/SM55

		Solarex	BP270	SM55	
WVT (gm/[m <sup>2</sup> -day])		8.21	3.98	3.64	
Thickness (um)		108	177	174	
Thickness of fluoride film (um)		96.8	40.3	40.5	
Structure					
Tensile strength (Mpa)		MD	46.52	93.52	95.06
		TD	73.18	110.65	127.59
breakage elongation (%)		MD	184.45	165.45	178.4
		TD	122.92	116.34	80.56
breakdown-voltage (kV)		6.66	15.66	15.83	
volume resistivity		1.964*10 <sup>16</sup>	1.266*10 <sup>16</sup>	1.364*10 <sup>16</sup>	

**Is moisture critical?**


**WVT is at least 3 times as much as the reference value.**

## Backsheet pulverization





Sample from Solarex module

New backsheet-Tedalar PV2001



2920-2960: -CH<sub>2</sub>-  
 1400-1000: C-F  
 1723: C=O  
 3400: hydroperoxide  
 580: Ti-O

- (a) Sample from Solarex module
- (b) Sample from Solarex module-covered by the label
- (c) Tedlar PV2001



Degradation mechanism:

Optical loss



Yellowness of EVA


Electrical loss



Moisture intrusion & micro crack



## Case2: Compare of Siemens modules from different climates



### **Mono module**

- Glass 3.2mm, EVA laminated
- Produce/installation time: 1992-1998
- Back-sheet: Tedlar/PET/Tedlar
- Cell thickness 320 $\mu$ m, size 101  $\times$  101mm
- Rated value:  $P = 55 \text{ Wp}$ ,  $V_{oc} = 21.7 \text{ V}$ ,  
 $I_{sc} = 3.45 \text{ A}$ ,  $V_m = 17.4 \text{ V}$ ,  $I_m = 3.15 \text{ A}$





## HISTORY SM55

- Procuce and installation: 1995
- Location:Shenzhen(1995-2014)  
18 ° 23'N, 108 ° 36'E
- Sub-humid heat climate
- Nearby the sea(<1000m)

## M75

- Procuce and installation: 1992
- Location:Shenzhen(1992-2015)  
38 ° 79'N, 93 ° 35'E
- **Cold-warm** climate
- Desert

Siemens modules produced during 1992–1998

Climates covers cold-warmI, cold-warmII and warm area



Dunhuang



Haixi



Zhangye



Longnan<sup>1</sup>



Baiyin



Longnan<sup>2</sup>

### Degradation compare of modules from different climates(STC)

SM55	Age	Qty	Pm/W	Im/A	Vm/V	Isc/A	Voc/V	FF
Rated value			55	3.15	17.4	3.45	21.7	0.73
Storage		1	51.6	3.03	17.0	3.35	21.6	0.71
Shenzhen	20	500	41.3	2.77	14.8	3.19	21.2	0.61

**6%**

**25%**

**7%**

**13%**

M75	Age	Qty	Pm/W	Im/A	Vm/V	Isc/A	Voc/V	FF
Rated Value			48	3.02	15.9	3.35	19.8	0.72
Dunhang	23	61	44.6	2.92	15.3	3.25	19.7	0.70
Haixi	23	41	41.8	2.77	15.1	3.14	19.6	0.68

**Relationship between degradation and climates?**


### Big deviation between STC and outdoor testing result

Dunhuang	Pmax	Voc	Vmpp	Impp	Isc	FF
Rated	48	19.80	15.90	3.02	3.35	0.72
STC	44.6	19.68	15.29	2.92	3.25	0.70
Outdoor	31.1	17.61	13.29	2.34	2.62	0.67


Haixi	Pmax	Voc	Vmpp	Impp	Isc	FF
Rated	48	19.80	15.90	3.02	3.35	0.72
STC	41.8	19.63	3.14	15.09	2.77	0.68
Outdoor	30.4	18.31	13.45	2.26	2.63	0.63

**Deviation: 30%**






M75





SM55



Why high series resistance?





SM55 Storage indoor



Structure of electron connection in front surface and back surface




Ag fingers on the front surface of solar cell



Fingers on the back surface of solar cell

Degradation mechanism:

Bad contact between solar cell and ribbon



Al-Ag paste/Soldering process/severe climate



# 4. Summary

- Degradation are caused by complex reasons, so it's hard to reach a conclusion. More data should be collected from different typical climates to study the effect of humidity, temperature and UV dose, salt mist, etc. to modules.
- The Solarex modules were firstly degraded by degradation of EVA(for loss of light transmittance), then by the crosion of fingers and ribbons. Power degradation of fielded modules is less than 10% for 28-year outdoor operation. Poly-Si modules show lower degradation rate than mono-Si modules.
- Accelerating test procedures should be optimized according to practice. New analysis method should be developed to test modules without damage.
- During work of reliability, it's important to announce the testing condition for it would cause big deviation.
- Lack of original information of PV modules and test conditions are great obstacles we met during study of degradation. So our test result could only supply a reference.

# Outlook

---

1. How to define module's life rationally? It's quite different from business warranty.
2. Select modules according to local circumstances. Meanwhile, standards of accelerating tests should be localization and detailed.
3. Mono-Si and poly-Si modules?
4. We are building a living fossil of fielded modules in order to track the degradate trend, it would be a reference to the testing dose and sequence.
5. No snail trails were found in these Siemens modules. Semiconductor is very stable theoritically, but is there any relationship between the module performance and cell thickness?

# Thanks for your attention!



Name: Xian Dong  
Email: [xiandong00@163.com](mailto:xiandong00@163.com)  
Tel: +86 18929971580