

Photos pending.

Item 5 Roof Covering (Old Wood Shake) – Old wood and cedar roof materials are a high ignition risk.

Note: Selected photographs are included to illustrate each HMM hardening item. Additional vulnerabilities or hardening items may be seen in the photographs, but those are highlighted within their specific HMM item.

There is no CAD drawing for
Item 5: Roof Covering (Old Wood Shake)

Please see photographs for illustrations.