



**Photo C-1. NIST Nain Entrance – Front of the House shown with library on the left side and auditorium on the right side of entrance (view southwest)**



**Figure C-2. Exposed Concrete Wall on West Elevation of Auditorium (view southeast)**



**Figure C-3. Concrete Spalling on West Elevation of Auditorium**



**Figure C-4. Detail of Auditorium Stone Wall**





**Figure C-5. North-Facing Exterior Door on the West Side of the Auditorium (view southwest). This door was replaced in 1981.**



**Figure C-6. Ramp to West Auditorium Stage Door, Stone and Brick Retaining Wall, and "Butterfly" Screen Wall (view northeast)**



**Figure C-7. Concrete Structure and Stone Walls on North Elevation of Auditorium (view southwest)**



**Figure C-8. Northeast Corner of Auditorium (view southwest)**





Figure C-9. Ramp to East Auditorium Stage Door, Stone and Brick Retaining Wall, and “Butterfly” Screen Wall (view northeast)



Figure C-10. Cornerstone in East Wall of the Auditorium (view west)



**Figure C-11. South Wall of Auditorium (view east)**



**Photo C-12. Roof over Auditorium (view northeast)**





**Figure C-13. Roof Drains and Membrane on Auditorium Roof (view northeast)**



**Photo C-14. North Elevation of Library (view west)**



**Photo C-15. Detail of North Elevation of Library (view southwest)**



**Photo C-16. West Elevation of Library (view south)**





**Photo C-17. East Elevation of Library (view north)**



**Photo C-18. South Elevation of Library (view north)**



**Photo C-19. Original Windows on South Elevation (view north)**



**Photo C-20. Building 1 Courtyard and Main Entrance to Lobby (view southwest)**





**Photo C-21. Vestibule and Main Entrance to Lobby (view west)**



**Photo C-22. Building 1 Courtyard (view south)**



**Photo C-23. Patched Columns in Courtyard**



**Photo C-24. West Elevation of Spine (view northeast)**





**Photo C-25. East Elevation of Spine (view northwest)**



**Photo C-26. West Elevation of Spine between Wings 3 and 5 (view northeast)**




**Photo C-27. Spine Window System**



**Photo C-28. Sunken Courtyard on West Elevation of Spine (view south)**





**Photo C.29. Roof of Spine (view northeast)**



**Photo C-30. South Elevation of the Rooftop Penthouse (view northeast)**



**Photo C-31. North Elevation of the Rooftop Penthouse (view southwest)**



**Photo C-32. 2017 Egress Stairway and Secondary Means of Egress on West Side of Penthouse and Spine (view southwest)**





**Photo C-33. South Elevation of the Spine between Wings 4 and 6 (view north)**



**Photo C-34. Orange Staining on Concrete and Replacement Windows on North Elevation of Wing 1 (view southeast)**



**Photo C-35. Original and Replacement Windows on North Elevation of Wing 1 (view southeast)**



**Photo C-36. Replacement Windows and Original Door on South Elevation of Wing 1 (view north)**





**Photo C-37. Replacement Windows and Original Door on South Elevation of Wing 1 Hyphen (view north)**



**Photo C-38. Original Windows on North Elevation of Wing 1**



Photo C-39. Original Door on North Elevation of Wing 1 (view southwest)



Photo C-40. Replacement Doors on North Elevation of Wing 1 (view southwest)





**Photo C-41. Downspouts on Wing 1**



**Photo C-42. Annex C and Connecting Hyphen on the West Side of Wing 1 (view southeast)**



**Photo C-43. Annex D South of Wing 1 (view southeast)**



**Photo C-44. Rooftop of Wing 1 and Annexes E and F (view west)**





**Photo C-45. Connections between Annexes D and E to the Rooftop of Wing 1 (view northwest)**



**Photo C-46. Annexes D and E (view northwest)**



**Photo C-47. South and East Elevations of Wing 2 (view north)**



**Photo C-48 North Elevation of Wing 2 (view southwest)**





**Photo C-49. Concrete Wall Detail with Horizontal Pour Line, Vertical Control Joint, and Orange Concrete Stains; Typical of Wings 1, 2, and 4.**



**Photo C-50. Replacement Windows on North Elevation of Wing 2 (view northwest)**



**Photo C-51. South Elevation of Wing 2 (view north)**



**Photo C-52. Doors on South Elevation of Wing 2 (view north); the single-leaf door on the left is a later addition and is not an original feature of Wing 2**





**Photo C-53. Loading Dock on the North Elevation of the Hyphen between the Spine and Wing 2 (view southwest)**



**Photo C-54. Loading Dock on the East Elevation of Wing 2 (view north); the cantilevered shade and the metal pipe railings are not historic features of this elevation**



**Photo C-55. View of Roof of Wing 2 from the Roof of the Spine (view south)**



**Photo C-56. North Elevation of Wing 3 (view west).**





**Photo C-57. North and West Elevations of Wing 3 (view south)**



**Photo C-58. South and East Elevations of Wing 4 (view north)**



**Photo C-59. Typical Wing 4 Exterior Bay (view southwest)**



**Photo C-60. South Elevation of Wing 4 (view east)**





**Photo C-61. Doors on South Elevation (view north); the single-leaf door on the left is a later addition and is not an original feature of Wing 2**



**Photo C-62. Door on North Elevation (view west)**



**Photo C-63. East Elevation of Wing 4 (view west); three original windows have been removed from the first bay**



**Photo C-64. Wing 4, South Elevation (view northwest)**





**Photo C-65. Wing 5, North Elevation (view southwest)**



**Photo C-66. Wing 5, South Elevation (view northeast)**



**Photo C-67. Metal Awnings on North Elevation (view southwest)**



**Photo C-68. Failed Original Concrete Canopy and Metal Awnings on North Elevation (view west)**





**Photo C-69. West Elevation of Wing 5 (view southeast)**



**Photo C-70. South and East Elevations of Wing 6 (view west)**



**Photo C-71. East Elevation of Wing 6 (view west)**




**Photo C-72. Auditorium Interior (view northeast toward stage and north wall)**





**Photo C-73. Auditorium Stage (view north)**



**Photo C-74. East Wall of Auditorium (view southeast)**



**Photo C-75. South Wall of Auditorium (view southwest)**



**Photo C-76. Detail of Base on East and West Walls**





**Photo C-77. Projection Room (view southeast)**



**Photo C-78. Portal to Auditorium (view northeast)**



**Photo C-79. Room 1107**



**Photo C-80. Room 1108**





**Photo C-81. Room 1201**



**Photo C-82. Room 1201A**



**Photo C-83. Room 1203**



**Photo C-84. Library Entrance (view northwest)**





**Photo C-85. Library Stacks (view southeast)**



**Photo C-86. West and North Walls (view north)**



**Photo C-87. Library Front Desk (view northeast)**



**Photo C-88. Library Support Room (view northeast)**





**Photo C-89. Wood Paneled Wall in Library (view southeast)**



**Photo C-90. Building 1 Main Entrance and Vestibule (view northeast)**



**Photo C-91. Interior Planting Area in Vestibule (view northeast)**



**Photo C-92. View of Lobby toward the Foyer in the West Division (view northwest)**





Photo C-93. Auditorium Entrance off of the Foyer (view northeast)



Photo C-94. West End of Foyer (view north)



**Photo C-95. South Wall of the Foyer between the Entrances to the Lecture Rooms (view west)**



**Photo C-96. North Wall of the Foyer between the Entrances to the Auditorium (view east)**







**Photo C-97. South Wall of Lobby (view southeast)**



**Photo C-98. Lobby Stairs to Levels 1 and 2 of the Spine (view southwest); the handrails were originally 1.5-inch steel pipe**



**Photo C-99. Lobby Stairs to Levels 1 and 2 of the Spine (view southeast); the handrails were originally 1.5-inch steel pipe**



**Photo C-100. Detail of Terrazzo**






**Photo C-101. View from the Lobby toward the Corridor in the East Division (view southeast)**



**Photo C-102. Corridor in East Division (view southeast)**



**Photo C-103. Corridor in East Division (view southeast)**



**Photo C-104. East End of Corridor and Former Location of Original Conference Room (view southeast; the doors and finishes in this area are not original)**





Photo C-105. Lobby Area in Level 2 of the Spine (view southwest)



Photo C-106. Lobby Area in Level 1 of the Spine (view southwest)



**Photo C-107. Restroom in Level 1**



**Photo C-108. Restroom in Level 1**





Photo C-109. Reception Area (view southwest)



Photo C-110 Electrical Switches in the Reception Area



**Photo C-111. Wood Wall Paneling in the Reception Area**



**Photo C-112. Room 1101B**





Photo C-113. Room 1101C



Photo C-114. Quartz Crystal Oscillator and Emmy Award Displays in Lobby (view north)



**Photo C-115. Plaque Listing Chamber of Commerce Donors in the Front of the House Corridor**



**Photo C-116. Award Display in the Front of the House Corridor**





Photo C-117. Cornerstone Monument on the East Exterior Wall of the Auditorium (view northwest)



Photo C-118. Dedication Plaque on the East Exterior Wall of the Auditorium (view northwest)



**Photo C-119. Former Cafeteria in Level 1 of the Spine (view southwest)**



**Photo C-120. Modern Metal Staircase in Sunken Terrace (view north)**






Photo C-121. Corridor between Former Cafeteria Area and Boiler Room (view southwest)



Photo C-122. Boiler Room Area in Level 1 of Spine (view southwest)



**Photo C-123. Double-Loaded Corridor on Level 2 of the Spine (view southwest)**



**Photo C-124. Original Door and Hardware within Level 2 of the Spine**





**Photo C-125. Newer Door within Level 2 of the Spine**



**Photo C-126. Upgraded Elevator within Level 2 of the Spine**



**Photo C-127. Double Loaded Corridor in Level 2 of the Spine, South of the Intersection of Wings 1 and 2 (view southwest)**



**Photo C-128. Interpretive Displays the Level 2 Spine Corridor**






Photo C-129. Interpretive Displays the Level 2 Spine Corridor




Photo C-130. Interpretive Displays the Level 2 Spine Corridor




Photo C-131. Interpretive Displays the Level 2 Spine Corridor



Photo C-132. Interpretive Displays the Level 2 Spine Corridor





**Photo C-133. Infilled Atomic Clock Viewing Window**



**Photo C-134. Painting at the South End of the Level 2 Corridor**



**Photo C-135. Level 3 Spine Corridor (view northeast)**



**Photo C-136. Level 3 Spine Corridor (view southwest)**





**Photo C-137. Typical Expansion Joint Cover**



**Photo C-138. Upgraded Elevator in Level 3 of the Spine**



**Photo C-139. Curtained Viewing Window in Level 4 of the Spine.**




**Photo C-140. Double-Loaded Corridor in Wing 1**






**Photo C-141. Original Doors in Wing 1**



**Photo C-142. Double-Loaded Corridor in Wing 2**



**Photo C-143. Original Doors in Wing 2**



**Photo C-144. Stairs to the Mezzanine Offices in Wing 2**





**Photo C-145. Double-Loaded Corridor in Wing 4**



**Photo C-146. Original Door and Asphalt Tile Flooring in Wing 4**



**Photo C-147. High Bay Laboratory Space in Wing 4**




**Photo C-148. Basement of Wing 5.**





**Photo C-149. Women's Restroom in Basement of Wing 5.**



**Photo C-150. Level 3 of Wing 5.**



**Photo C-151. Level 5 (Monitor Level) of Wing 5.**



**Photo C-152. Wing 3 Interior**





**Photo C-153. Wing 6 Interior**



**Photo C-154. Spalls at Steel Embed**



**Photo C-155. Water Exposure and Cracks**



**Photo C-156. Cracks**





**Photo C-157. Sunshade Staining**



**Photo C-158. Column Cracks and Stains**



**Photo C-159. Cracking at Top of Column**




**Photo C-160. Cracks in Wall**





**Photo C-161. Cracks in Roof Beam**



**Photo C-162. Spall at Rusted Rebar**



**Photo C-163. Column Cracks**



**Photo C-164. Deterioration of Existing Canopy**