

This document has been accepted by the Academy Standards Board (ASB) for development as an American National Standard (ANS). For information about ASB and their process please refer to asb.aafs.org. This document is being made available at this stage of the process so that the forensic science community and interested stakeholders can be more fully aware of the efforts and work products of the Organization of Scientific Area Committees for Forensic Science (OSAC). The documents were prepared with input from OSAC Legal Resource Committee, Quality Infrastructure Committee, and Human Factors Committees, as well as the relevant Scientific Area Committee. The content of the documents listed below is subject to change during the standards development process within ASB, and may not represent the contents of the final published standard. All stakeholder groups or individuals, are strongly encouraged to submit technical comments on this draft document during the ASB's open comment period. Technical comments will not be accepted if submitted to the OSAC Scientific Area Committee or Subcommittees.

Standard for 3D Measurement Systems and Measurement Quality Control for Firearm and Toolmark Analysis



DRAFT DOCUMENT

Standard for 3D Measurement Systems and Measurement Quality Control for Firearm and Toolmark Analysis

Keywords: *3D, Topography, Measurement, Quality Assurance, Traceability, Firearms, Toolmarks, Identification*

This document applies to all 3D imaging systems (the instrument and included scan acquisition software) which capture data beyond a flat 2D photographic image. This document is intended to ensure the instrument's accuracy, to conduct instrument calibration, and to estimate measurement uncertainty for each axis (X, Y, and Z).

DRAFT

Foreword

This standard was proposed by the Firearms and Toolmarks Subcommittee of the Organization of Scientific Area Committees (OSAC) by submitting a request to the American Academy of Forensic Sciences (AAFS) Academy Standards Board (ASB).

This document is part of a series of documents jointly submitted to include:

1. Standard for 3D Measurement Systems and Measurement Quality Control for Firearm and Toolmark Analysis
2. Standard for Topography Comparison Software for Firearm and Toolmark Analysis
3. Standard for Implementation of 3D Technologies in Forensic Laboratories for Firearm and Toolmark Analysis

The purpose of these standards is to ensure that new technologies produce accurate measurements and a validated statistical assessment of the significance of the correspondence. The documents establish performance expectations for new technologies while allowing legacy systems to coexist in the lab. The hardware document specifically refers to 3D scanning hardware and does not apply to legacy 2D type systems. The software document specifies three categories (levels) of software. Legacy systems are Category 0 whereas systems which provide validated statistical measures are Category 2. The implementation document outlines the necessary steps to ensure the proper implementation of 3D technologies.

DRAFT

Acknowledgements

Editor:

Deputy Editor(s):

Drafting Working Group Members:

Ryan Lilien	Cadre Research Labs - Chicago, Illinois
Nicholas Petraco	John Jay College of Criminal Justice - New York, New York
Erich Smith	Firearms/Toolmarks Unit - Federal Bureau of Investigation (FBI) - Quantico, Virginia
Todd Weller	Weller Forensics - Burlingame, California
Xiaoyu Zheng	Engineering Physics Division - National Institute of Standards and Technology (NIST) - Gaithersburg, Maryland

Consensus Group Members:

DRAFT

Table of Contents

Acknowledgements	iv
Table of Contents	v
1 Scope.....	1
2 Normative References	1
3 Terms and Definitions	1
4 Requirements	3
4.1 Developmental Validation (Mandatory)	3
4.2 Deployment Validation (Mandatory)	4
4.3 Ongoing Performance Checks (Mandatory)	5
4.4 Measurement Traceability (Mandatory)	6
4.5 Data Exchange Format XML 3D Profile (X3P) (Mandatory)	6
5 Conformance	7
Annex A	8

DRAFT

1 Scope

This document applies to all imaging systems (the instrument and included scan acquisition software) which capture data beyond a flat 2D photographic image; in the remainder of this document these systems are referred to as 3D systems. This document is intended to ensure the instrument's accuracy, to conduct instrument calibration, and to estimate measurement uncertainty for each axis (X , Y , and Z). The focus of this standard is on the hardware and resulting measurement data. This standard is applicable to all forensic science service providers that provide conclusions regarding toolmark related evidence.

2 Normative References

ASCLD/LAB AL-PD-3057 Ver 1.3 -- *ASCLD/LAB Policy on Measurement Traceability*.

BIPM -- "*Evaluation of measurement data — Guide to the expression of uncertainty in measurement*," JCGM 100:2008

ISO 25178-6:2010 Geometrical product specifications (GPS) -- Surface texture: Areal -- Part 6: *Classification of methods for measuring surface texture*.

ISO 25178-72 Geometrical product specifications (GPS) -- Surface texture: Areal -- Part 72: *XML file format x3p*

3 Terms and Definitions

3.1

areal-topography method¹

Surface measurement method that produces a topographical image of a surface, which may be represented mathematically as a height function $z(x, y)$ of two independent variables (x, y)

3.2

Coherence Scanning Interferometry¹

CSI

Surface topography measurement method wherein the localization of interference fringes during a scan of optical path length provides a means to determine a surface topography map.

3.3

confocal microscopy¹

Surface topography measurement method whereby a pinhole object illuminated by the light source is imaged by a lens onto the surface being studied and the light is reflected back through the lens to a second pinhole placed in front of a detector and acting as a spatial filter.

¹ ISO 25178-6:2010 Geometrical product specifications (GPS) -- Surface texture: Areal -- Part 6: *Classification of methods for measuring surface texture*.

3.4

confocal chromatic microscopy¹

Surface topography measurement method consisting of a confocal microscope with chromatic objective integrated with a detection device (e.g., spectrometer) whereby the surface height at a single point is sensed by the wavelength of light reflected from the surface.

3.5

dropouts

Ordinate values within a dataset that did not receive enough signal during the measurement for a height measurement to be acquired. These are often represented as NaN, zero, blank, or the minimum measured value.

3.6

focus variation microscopy¹

Surface topography measurement method whereby the sharpness of the surface image (or another property of the reflected light at optimum focus) in an optical microscope is used to determine the surface height at each position along the surface.

3.7

measurement coordinate system¹

System of coordinates that represent the geometry of the measured surface.

NOTE: If the nominal surface is a plane (or portion of a plane), it is common to use a rectangular coordinate system in which the axes form a right-handed Cartesian set, the X-axis being the direction of tracing co-linear with the mean line, the Y-axis also lying on the nominal surface, and the Z-axis being in an outward direction (from the material to the surrounding medium).

3.8

noise

High frequency signals caused by the instrument electronics, vibrations, and environmental factors. This is often determined by measuring a flat surface (e.g., mirror) which establishes the minimum feature height (z) that the instrument is capable of measuring. Also known as "Noise Floor".

3.9

ordinate value $z(x, y)$ ¹

Height of the surface at position (x, y) .

3.10

outliers

Ordinate values within a dataset that received an erroneous signal during the measurement and no longer represent the real surface. These often appear as spikes in the dataset. Detection methods include local slope and neighboring height thresholding.

¹ ISO 25178-6:2010 Geometrical product specifications (GPS) -- Surface texture: Areal -- Part 6: *Classification of methods for measuring surface texture.*

3.11

Phase-Shifting Interferometric Microscopy¹

PSI

Surface topography measurement method whereby an optical microscope with illumination of a known effective wavelength is integrated with an interferometric attachment and produces multiple successive optical images with interferometric fringes from which the profile or areal surface topography image is calculated.

3.12

photometric stereo

Surface topography measurement method in computer vision for measuring the surface normals of a surface by observing that surface under different lighting conditions. Given sufficient independent light sources, the surface normals, and thus surface geometry, can be determined for every position on the surface.

3.13

processed data

Ordinate values that have been processed (e.g., trimmed, filtered, and/or interpolation applied).

3.14

raw data

Ordinate values that come directly from the instrument which have not been manipulated (e.g., trimmed, filtered, and/or interpolation applied).

3.15

reference datafile

A reference measurement of a flat surface (e.g., mirror) which includes the errors and optical aberrations of the measurement system. This data file can be stored and subtracted from all subsequent measurements.

3.16

structured light projection¹

Surface topography measurement method whereby a light image with a known structure or pattern is projected on a surface and the pattern of reflected light together with knowledge of the incident structured light allows one to determine the surface topography.

3.17

surface profile¹

Profile that results from the intersection of the real surface by a specified plane.

4 Requirements

4.1 Developmental Validation (Mandatory)

As per the “Standard for Implementation of 3D Technologies in Forensic Laboratories for Firearm and Toolmark Analysis,” a developmental validation shall be completed by at least one organization

¹ ISO 25178-6:2010 Geometrical product specifications (GPS) -- Surface texture: Areal -- Part 6: *Classification of methods for measuring surface texture.*

with appropriate knowledge and/or expertise. The developmental validation of imaging hardware typically consists of identifying and citing previously published scientific literature establishing the underlying imaging technology.

4.2 Deployment Validation (Mandatory)

As per the “*Standard for Implementation of 3D Technologies in Forensic Laboratories for Firearm and Toolmark Analysis*,” the laboratory shall complete a deployment validation prior to use in casework.

4.2.1 Personnel

Personnel responsible for deployment validation shall at a minimum have a bachelor's degree or equivalent degree with a natural science-based or applied science-based major field of study. To the extent possible, a single individual should conduct all components of the deployment validation to minimize sources of operator uncertainty.

4.2.2 Environmental Conditions

To ensure quality measurements, the instrument should be in a low noise and low vibration environment. Air vents and high traffic areas of the building should be avoided. Some instruments (e.g., interferometry) are extremely sensitive to vibrations and should reside on a vibration isolation table (active or passive). To determine the “noise floor” of the instrument, see section 4.2.4.1.

4.2.3 Instrument Calibrations

The laboratory shall have the instrument calibrated by the manufacturer or instrument provider upon installation.

4.2.4 Minimum Requirements for Establishing/Verifying Instrument Performance

The deployment validation for a new 3D measurement instrument shall verify and document the instrument's performance. These tests are required after initial installation and after any subsequent hardware modification or location change that affect the scanning process (e.g., after the installation of a new objective or relocation to a new environment). The deployment validation includes:

4.2.4.1 Instrument Noise Floor Testing

Noise floor testing shall be conducted using a flat surface (e.g., mirror) with flatness better than $\lambda/10$, where λ is the wavelength of the light source. Ten measurements shall be performed consecutively without changing the measurement setup. Ten measurements shall also be performed daily over ten days. The calculated average roughness (Sa) value shall be within manufacturer specifications. For 3D instruments that rely on a minimum level of roughness to resolve the surface (i.e. focus variation), the noise floor should be tested using manufacturer suggested standards and protocols.

4.2.4.2 Instrument Repeatability Measurement

Using calibrated geometric standards (e.g., sine wave, pitch, step heights), measurements shall be conducted to check the X and Y lateral scales as well as the vertical Z scale. Ten measurements shall be performed consecutively without changing the measurement setup (i.e., not taking the sample off the instrument, not changing the operator, and not varying any measurement parameters). The measurement uncertainty of the repeatability measurements must overlap with the certified value and uncertainty of the geometric standard used.

4.2.4.2.1 X and Y Lateral Scale Check

The X and Y lateral scales shall be checked using a geometric standard calibrated for a length scale parameter such as pitch or RSm (wavelength).

4.2.4.2.2 Z Vertical Scale Check

The Z scale shall be checked using a geometric standard calibrated for height in standard units.

4.2.4.3 Instrument Reproducibility Measurement

Using calibrated geometric standards (e.g., sine wave, pitch, step heights), check measurements shall be conducted to test the X and Y lateral scales as well as the vertical Z scale. Daily measurements shall be performed over ten days by the same operator. The measurement setup shall be varied each day (i.e., taking the sample on and off the instrument and manually setting up each measurement). The measurement uncertainty of the reproducibility measurements must overlap with the certified value and uncertainty of the geometric standard used.

4.2.4.3.1 X and Y Lateral Scale Check

The X and Y lateral scales shall be checked using a geometric standard calibrated for a length scale parameter such as pitch or RSm (wavelength).

4.2.4.3.2 Z Vertical Scale Check

The Z scale shall be checked using a geometric standard calibrated for height in standard units.

4.2.4.4 Instrument Measurement Uncertainty

The laboratory shall document the instrument's X, Y, and Z measurement uncertainties in accordance with the "*Evaluation of measurement data — Guide to the expression of uncertainty in measurement*"¹. Laboratories may also have to comply with their accrediting body requirements for uncertainty in measurement. These uncertainties can often be determined using the procedures stated in section 4.2.4.2 and 4.2.4.3.

4.3 Ongoing Performance (Mandatory)

¹ BIPM -- "*Evaluation of measurement data — Guide to the expression of uncertainty in measurement*," JCGM 100:2008

As per the “*Standard for Implementation of 3D Technologies in Forensic Laboratories for Firearm and Toolmark Analysis*,” the laboratory shall document and demonstrate measurement Quality Control (QC) procedures and measurement traceability.

4.3.1 Check and Re-Check Measurement

The check and re-check measurements bracket regular measurements. These measurements shall be conducted at the beginning and end of the data acquisition session. These should include at a minimum a check and re-check for the X, Y, and Z scale. The purpose is to ensure that regular measurements are traceable and that the instrument did not drift during the measurements.

4.3.2 Control Chart

The laboratory shall maintain a control chart [1] tracking all measured re-check measurement values. The control chart shall display the calibrated uncertainty values for each standard and the dated re-check measurement results. Out of spec re-check measurements shall be documented in the control chart.

4.3.3 Quality Control Failure Protocol (Mandatory)

If the measured check and re-check value falls out of the control limits, a minimum of two repeat measurements shall be made to eliminate the chance of an outlier. The failed check values shall be noted on the control chart.

If the error persists, then it shall be removed from service until it can be repaired and recalibrated by an accredited calibration provider (or in-house as applicable). The data collected while in noncompliance of the quality control check (i.e. the compromised measurement session) cannot be guaranteed and shall not be used. The qualified personnel that conducted the instrument validation should, to the best of their ability, diagnose and correct the source(s) of error (e.g. environment, algorithm, protocol, measurement/sample quality, user). If the error diagnosis is inconclusive, the instrument manufacturer or qualified expert should be involved in the investigation.

4.4 Measurement Traceability (Mandatory)

The geometric standards used for instrument performance validation (Section 4.2.4) and quality control measurements (Section 4.3) shall be metrologically traceable to the SI unit of length. Metrological traceability is defined as a result that can be related to a reference through an unbroken chain of calibrations, each contributing to the measurement uncertainty. For more information on traceability, see section 2.1 of ASCLD/Lab policy¹ on Measurement Traceability.

The laboratory shall document the traceability chain of the geometric standards used. This can be supplied by the manufacturer or the accredited calibration laboratory.

4.5 Data Exchange Format XML 3D Profile (X3P) (Mandatory)

¹ ASCLD/LAB AL-PD-3057 Ver 1.3 -- *ASCLD/LAB Policy on Measurement Traceability*.

Any imaging hardware that collects data of dimensions greater than two shall support full resolution raw data in XML 3D Profile (X3P) format in accordance to ISO 25178-72¹. More information as well as minimum metadata requirements can be found in the “*Standard for Topography Comparison Software for Firearm and Toolmark Analysis*” standard.

5 Conformance

Conformance with this *Standard for 3D Measurement Systems and Measurement Quality Control for Firearm and Toolmark Analysis* document will be accessed utilizing these documents:

ASCLD/LAB-International Supplemental Requirements for the Accreditation of Forensic Science Testing Laboratories, American Society of Crime Laboratory Directors/Laboratory Accreditation Board, Garner, NC, 2011.

ISO/IEC 17025 - General Requirements for the Competence of Testing and Calibration Laboratories, International Organization for Standardization, Geneva, Switzerland, 2005.

DRAFT

¹ ISO 25178-72 Geometrical product specifications (GPS) -- Surface texture: Areal -- Part 72: *XML file format x3p*

Annex A
(informative)

Bibliography

- 1] Guide to control charts by the American Society for Quality available for free at <http://asq.org/learn-about-quality/data-collection-analysis-tools/overview/control-chart.html>

DRAFT