

**DAMAGE ASSESSMENT REPORT**

**1 COLLECTION DETAILS**

Incident Name: Camp Fire      Recording Date: 12, 2, 18      Time Recorded: 11:55a  
Photo Release Form Approved:  Yes  No  N/A      Photo Numbers: 1997-2110

**2 ADDRESS**

Fixed       RV/Travel Trailer       Manufactured Home

[Redacted]  
Street Number      Street Name      Unit No.  
Paradise      CA  
City      State      ZIP

Property Owner Last Name (if known)

**3 DAMAGE TO STRUCTURE**

Extent of Damage:  Affected       Minor       Major       Destroyed       No Damage

Ignition/Damage Exposure Type:  Embers       Radiation / Convection       Undetermined

**Damaged Feature Assessment:**

Feature	Damaged	Feature	Damaged	Feature	Damaged
Roof	<input type="checkbox"/>	Eaves	<input checked="" type="checkbox"/>	Windows	<input checked="" type="checkbox"/>
Roof Valley / Transitions	<input type="checkbox"/>	Gutters	<input type="checkbox"/>	Doors	<input type="checkbox"/>
Dormers	<input type="checkbox"/>	Siding/Walls <i>force connection</i>	<input checked="" type="checkbox"/>	Decking	<input type="checkbox"/>
Window Details:	<input type="checkbox"/> Single Pane <input checked="" type="checkbox"/> Double Pane - broken <i>some both panes</i>	<input type="checkbox"/> Frame Damage <input checked="" type="checkbox"/> Seal Damage	<input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Fiberglass	<input type="checkbox"/> Wood <input type="checkbox"/> Other	<input type="checkbox"/> Metal <input type="checkbox"/> N/D
Door Details:	<input type="checkbox"/> Window Damage <input type="checkbox"/> Door Damage	<input type="checkbox"/> Frame Damage <input checked="" type="checkbox"/> Seal Damage <i>patio doors</i>	<input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Fiberglass	<input type="checkbox"/> Wood <input type="checkbox"/> Other	<input type="checkbox"/> Metal <input type="checkbox"/> N/D
Decking Details:	<input type="checkbox"/> Top Side <input checked="" type="checkbox"/> Posts <input type="checkbox"/> Bottom Side		<input type="checkbox"/> Wood	<input type="checkbox"/> Composite	<input type="checkbox"/> Other

**4 NOTES/DESCRIPTION**

(brief description of damage, general observations, details for Section 3)

- defended
- many cracked windows, some with both panes
- many different ignitions on all sides of house
- shed burned out behind
- horses on 4 sides burned out

# 5 PARCEL SKETCH

1. Document address
2. Form photo
3. Street 360
4. Damage 360
5. Damage detail
6. Mark distances to potential exposures
7. Evaluate wind direction (if possible)
8. Sketch

